








Ionic Foot Bath Safety Comparison Chart

	 IonCleanse®	 Spa Cleanse	 Cell Spa	 Aqua Chi	 Wellspring/Bella Products ¹	 Aqua Detox ²	 eSpa (B.E.S.T. Unit)
Product Safety Evaluation - IEC 60035-1	Pass	FAIL	FAIL	FAIL	FAIL	FAIL	FAIL
Radiated Emissions Test	Pass	FAIL	FAIL	Pass	Pass	Pass	Pass
Flammability Rated (UL94V-1)	Pass	FAIL	FAIL	FAIL	FAIL	Pass	Pass
Accessibility of Hazardous Voltage Test	Pass	Pass	FAIL	FAIL	Pass	FAIL	FAIL
Leakage Current Test	Pass	Pass	FAIL	FAIL	Pass	FAIL	FAIL
CE Cleared	YES	NO	NO	NO	NO	YES	NO
Place of Manufacture	Colorado	China	China	Alabama	Texas/Louisiana	United Kingdom	Nevada

¹The Wellspring/Bella Spa Products unit pictured above is described on the manufacturer's website as the portable device selling for \$1,395. It is important to note that older versions of this unit failed all of the tests. It is not clear when the unit was improved.

²The Aqua Detox unit received a CE rating from an agency in Europe. However, because this testing occurred in the United States, it failed several of the tests based on US standards.